TROY S. W. SECTION PLAT NO: 25

SCALE 1" = 40' FEET

PARCEL NUMBER
D08-_ _ _ _ _ _

REC. BK. 1 PG. 146

DRURY 60' R/W. LANE

60' R/W. STREET

GRANT

DRURY LANE

66' R/W.

PLUM STREET

10' PUBLIC ALLEY

2' PUBLIC ALLEY

SIMPSON 40' R/W. ST.

511 01300

512 01200

513 01100

Judith A. Nicktas D.B. 613-774

Katherine Blauser 2020OR-17248

PT. 528 LOT BK. 13 PG. 140 O.B. 514-461 Kim Bulko & Rodrigo Galindez 6R473-282

514 Justin M. Braun 20200R-05489

D.B. 538-372

515 01000 Joshua B. & Beth A. JACOMET, Co Trustees 20160R-04265

Pt. 516 01700 GARY J. & MELISSA A. NIDAY D.B. 604-736 T.O.D. 20180R-15783

Pt. 516 WILLIAM T. 2020R-07412

Pt. 516 Strecker 2016OR-14983

Pt. 517 01900 Christopher & Kassandra Bateman 2018OR-11275

Pt. 517 01900 Ram Rentals, LLC 0R451-818

Pt. 517 D08-028150 KATHLEEN A. PATRICK

Pt. 517 Cassandra 02100

Lot 9-47 00500 Frederick T. & Sarah J. Florence 0R454-979

PT. 529 Charles E. & Karen S. Wright DB 190-562

PT. 530 Karen & Paul Bradley

PT. 530 E. ALLEN & NANCY E. ANDERSON TRUSTEES SUR. VOL. 9 PG. 47 O.B. 532-564 DB 732-520

PT. 530 20180R-06764

PT. 531 Marjorie S. Eaton 20140R-07574

PT. 532 LND 57-61 0.387 AC. TOTAL Benjamin E. & Meghan E Denlinger 2016OR-08234

PT. 533 Robert M. Harrelson D.B. 568-784

PT. 533 SUZANNE L. ROYER DB 787-650

836

Note: The description on D.B. 604-736 has an erroneous distance called out for the tie to the Southwest corner of lot number 517. This should be revised on the next transfer.

REVISED: 6-1-21 MSS